

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

**Name of the School** : Holy Trinity Vidyabhavan Senior Secondary School,  
Karthikappally

1. Name of the Officer : ARATHY.S

2. Location : Hoaiipad / Alappuzha

3. Period for which the certificate is issued : 2024 - 2025

4. Types of building : North Block (GF, FF) - 57.57 x 9.87 x 3.60m }  
48.65 x 9.87 x 3.60m } 2 Nos  
18.50 x 8.05 x 3.60m }

5. Nature of defect if any

a) Foundation and basement }  
b) Superstructure } nil  
c) Doors and windows }  
d) Wood work wrought and put up }  
e) Roof }  
f) Flooring }  
g) Miscellaneous (Cracks if any) : Minor cracks on non-load bearing walls and minor leakage on RCC roof of verandah portion of North Block

6. Any Major defects notices which will render the building unsafe in any manner : No

7. Whether maintenance works have been done properly :

8. Whether the structure is sound or not for conducting classes : Yes, the structure is sound for conducting classes under normal weather conditions.

Note:-

- The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
- Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.
- Any trees in dangerous situation at the school premises has to be removed from the site at your own risk. Accidents caused by the same will be your sole responsibility.

*Latha B Nair*  
Principal  
Holy Trinity Vidyabhavan  
Karthigappally  
Pin: 690 516

*Thomas A. V. Thomas*  
Manager  
Holy Trinity Vidyabhavan  
Karthigappally

## CERTIFICATE

Certified that the School was inspected by me on .... 31/05/2024 .....  
and found to be fit / ~~unfit~~ to conduct classes for the period .... 2024 ... 2025 .....  
for the reason stated above.

Place: ... Chingoli .....  
Date: .... 31/05/2024 .....



*Arathy S*  
31/5/24  
Assistant Engineer  
LS&SD Section  
Chingoli G.P.