

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re. G.O. Ms. 20/70/PWD Dt. 23-01-1970)

Name of the School

Holy Trinity vidyabhavan

1. Name of the Officer
2. Location
3. Period for which the certificate is issued
4. Types of building
5. Nature of defect if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks if any)
6. Any Major defects notices which will render the building unsafe in any manner
7. Whether maintenance works have been done properly
8. Whether the structure is sound or not for conducting classes

: Nisha Sukumaran
: Karthikappally P.O, Alappuzha
: 2023-24
: North Block GF-56.70 x 9.65,
47.20 x 8.50 } 1127.6
18.78 x 8.11 } m²
Others - 264.43 m²
FF - 56.70 x 9.65 }
47.20 x 8.50 } 1127.64 m²
18.78 x 8.11 }
SF - 56.70 x 47.20 x 8.50 } 1093.95
18.78 x 8.11 }
Total - 3613.66 m²
South block
GF, FF, S.F
3 (26.54 x 6.88, 6.86 x 5.88,
26.5 x 8.40, 3.45 x 4.20) others
Total - 1492.71 m² 37.08 m²

Nil

Note: 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Latha B Nair
Principal
Holy Trinity Vidyabhavan
Karthigappally P.O
Pin: 690 516


Thomas A. V.
A. V. Thomas
Manager
Holy Trinity Vidyabhavan
Karthigappally

CERTIFICATE

Certified that the School was inspected by me on 29/5/2023
and found to be fit / unfit to conduct classes for the period 2023-24
for the reason stated above.

Place: Chingoli

Date: 29/5/2023



M. P. P.
29/5/23
Assistant Engineer
LSGD Section
Chingoli Grama Panchayath